## Amendments to the Specification:

Please replace paragraph [0020] with the following rewritten paragraph:

[0020] The sealing of the divider means 18 against the counter-surfaces can also be done hydraulically according to Figure 11. In it, all spring forces described above can be replaced by oil pressure in an oil channel arrangement 44, for instance by leading oil in through a channel 45 channel 45a and out through a channel 46. channel 45b. The springs 39, 41 and 43 described above or some of them can also be kept in addition to this hydraulic action to obtain a tight sealing even at the start-up time of the motor when the oil pressure has not risen sufficiently.